


Dobierze właściwą uszczelkę głowicy cylindrów dla 2,0-litrowych silników wysokoprężnych Ford EcoBlue

1. generacja 2015-2018 | numer części bloku: GK2Q-6010-AC



0,671-0,720		2 048 131	GK2Q 6051 FA
0,721-0,770		2 048 139	GK2Q 6051 GA
0,771-0,820		2 048 143	GK2Q 6051 HA
0,821-0,870		2 048 150	GK2Q 6051 JA
0,871-0,940		2 048 157 2 213 835	GK2Q 6051 KA HG9Q-6051-AA



-	1,30	-
-	1,35	-
-	1,40	-
-	1,45	-
806.450	1,50	



Ford EcoBlue

2. generacja 2018 -> | numer części bloku: GK2Q-6010-AD

Aluminiowy
tłok

Stalowy
tłok



0,835-0,884	0,885-0,934		2 213 835 2 048 157	HG9Q-6051-AA GK2Q 6051 KA
0,885-0,934	0,935-0,984		2 213 837	HG9Q-6051-BA
0,935-0,984	0,985-1,034		2 213 839 2 670 021	HG9Q-6051-CA HG9Q-6051-LA
0,985-1,034	1,035-1,084		2 213 841 2 670 025	HG9Q-6051-DA HG9Q-6051-MA
1,035-1,084	1,085-1,134		2 213 843 2 670 027	HG9Q-6051-EA HG9Q-6051-NA
-	-		2 213 845	HG9Q-6051-FA
-	-		2 213 847	HG9Q-6051-GA HG9Q-6051-RA
-	-	-	2 670 036	HG9Q-6051-SA
-	-	-	-	HG9Q-6051-TA



806.450	1,50		-
806.460	1,55		(5)
806.470	1,60		(4)
806.480	1,65		(3)
806.490	1,70		(2)
806.540	1,75		(1)
806.560	1,80		(1)+(2)
-	1,85	-	-
-	1,90	-	-

ElringKlinger AG | Aftermarket Division

Max-Eyth-Straße 2 | D-72581 Dettingen/Erms

Fon +49 7123 724-799 | Fax +49 7123 724-798

service@elring.de | www.elring.com

SI 09/2024



Das Original